

2nd attempt – Feed B2B leisure out direct to leisure battery

Omit the Eng + connection on HTM-01

This works apart from the engine battery monitor is missing on main display and there is no D+ connection so fridge doesn't work on 12V

The charge rate on the leisure battery is much higher than the engine battery which I have taken to be correct operation.

