


Autotrail Cheyenne 6969 N<sup>o</sup>. 10083, 2005.

Richard Casselle.



- Bottom timber edge to back panel rotted.

- Bottom part of ply fascia rotted.

- Rearmost timber edge and longitudinal timber braces rotted.

- Front NS corner of floor panel rotted

- Ply surface rotted.